

ROTATION FACING LOAD END	L1	L2	JOIN & INSULATE
C.C.W ROT.	P1	T4 T5	P3.T1 T8
C.W ROT.	P1	T4 T8	P3.T1 T5